

Technical Bulletin.

PAD1198, PAD1259 & PAD1269 Overlapping Friction Material

At Apec we pride ourselves in following the OE design and specification for the products that we supply. Full Spec. Full Stop.

This is why the friction material on PAD1198, PAD1259 and PAD1269 is overlapping the backing plate as per the OE design and is not a manufacturing defect.

